





Lista Airbag - aggiornamento 22/08/2008

Marca	Modello	ECU	MICRO - MEMORIA
 <h3>ALFA ROMEO</h3>			
Alfa Romeo	145	46538798 TRW	68HC11KA4
Alfa Romeo	146	60631206 TRW	68HC11E9
Alfa Romeo	147	46842421 5WK43277	95080
Alfa Romeo	147	46805905 TRW	24LC04
Alfa Romeo	147	46813473	68HC08AS32
Alfa Romeo	156	43055365	68HC08AS20
Alfa Romeo	156	46409123 Allied Signal	68HC11E9
Alfa Romeo	156	60675876	68HC908AS60
Alfa Romeo	156	60626560	68HC11KA4
Alfa Romeo	156	60656767	68HC11E20
Alfa Romeo	156	60658009	68HC08AS20
Alfa Romeo	156	60683300	95080
Alfa Romeo	156	60663040	68HC08AS20
Alfa Romeo	156	60664962	68HC08AS20
Alfa Romeo	156	60665492	68HC08AS20
Alfa Romeo	156	60669250	68HC08AS20
Alfa Romeo	156	60680213	95080
Alfa Romeo	156	60668390	68HC08AS20
Alfa Romeo	156	60692059 TRW	25LC320
Alfa Romeo	159	60692059 TRW	25LC320
Alfa Romeo	159	60692060 TRW	25LC320
Alfa Romeo	159	50507543 TRW	25LC320
Alfa Romeo	159	50507544 TRW 391166	25LC320
Alfa Romeo	166	60678004 TRW	24LC04
Alfa Romeo	GTV	60625181 TRW	68HC11E9


Auto Consulting

Alfa Romeo	GTV	60664500 TRW	68HC11KA4
Alfa Romeo	Spyder	60694761 TRW 391076	25LC320
 AUDI			
Audi		4A0 959 655 Bosch 0 285 001 036	93C46
Audi		4B0 959 605 Q Bosch 0 285 001 486	CR16
Audi		4B0 959 655 AC Bosch 0 285 001 704	68HC912B32
Audi		4B0 959 655 C Bosch 0 285 001 106	68HC11KA4
Audi		4B0 959 655 J Bosch 0 285 001 307	68HC11KA4
Audi		4D0 959 655 A prod MBB	68HC11E9
Audi		4D0 959 655 C Bosch 0 285 001 150	68HC11KA4
Audi		4D0 959 655 J Bosch 0 285 001 307	68HC11KA4
Audi		4D0 959 655 prod MBB	68HC11E9
Audi		4F0 959 655 B Siemens 5WK43416	95160
Audi		8A0 959 655 A Bosch 0 285 001 086	68HC11E9
Audi		8A0 959 655 B Bosch 0 285 001 037	68HC11E9
Audi		8A0 959 655 Bosch 0 285 001 085	68HC11E9
Audi		8A0 959 655 C Bosch 0 285 001 038	68HC11E9
Audi		8A0 959 655 D Bosch 0 285 001 039	68HC11E9
Audi		8A0 959 655 K Bosch 0 285 001 151	68HC11E9
Audi		8A0 959 655 K Bosch 0 285 001 155	68HC11E9
Audi		8D0 959 655 L Bosch 0 285 001 305	68HC11K4
Audi		8D0 959 655 C Bosch 0 285 001 176	68HC11K4
Audi		8E0 959 655 Bosch 0 285 001 400	CR16MCS9
Audi		8E0 959 655 B Bosch 0 285 001 483	CR16MCS5
Audi		8E0 959 655 G Bosch 0 285 001 668	95640
Audi		8L0 959 655 C Bosch 0 285 001 176	68HC11KA4
Audi		8L0 959 655 C Bosch 0 285 001 304	68HC11KA4
Audi		8L0 959 655 G Bosch 0 285 001 352	68HC912B32
Audi		8L0 959 655 F Bosch 0 285 001 304	68HC11KA4
Audi		8L0 959 655 J Bosch 0 285 001 352	68HC912B32
Audi		8L0 959 655 L Bosch 0 285 001 352	68HC912B32

Auto Consulting

Audi		8P0 959 655 D Bosch 0 285 001 700	CR16MCS9
Audi		8Z0 959 655 G Bosch 0 285 001 698	68HC912B32
Audi	A3	8L0 959 655 C Bosch 0 285 001 261	68HC11E20
Audi	A4	8E0 959 655 J Bosch 0 285 001 691	CR16MCS5
Audi	A4	8H0 959 655 B Bosch 0 285 001 652	CR16MCS5
Audi	A8	4D0 959 655 T Bosch 0 285 001 405	68HC912B32
 <h3 style="margin: 0;">BMW</h3>			
BMW	320	837252 MRSZ2 12 9441	68HC11KA4
BMW	320	3169 3323800A - 0285001681	68HC912D60
BMW	320	3169 62531006 - 0285001682	68HC912D60
BMW	E36	6577 8367035	68HC11E9
BMW	E39	6577 6912123 - 0285001440	68HC912D60
BMW	E39	6577 6912755 - 0285001681	68HC912D60
BMW	E39	6577 8372521 Temic	68HC11KA4
BMW	E39	6577 6919789 Temic (G8T2G12ABH0 or GAT2G10ACE0)	68HC912D60
BMW	E46	G2T0J21B197 Temic 6577 6900727	68HC912AB32
BMW	E46	0 285 001 458 Bosch 6577 6912755	68HC912D60
BMW	X5	0 285 001 458 Bosch	68HC912D60
BMW	Z3	6577 6910677 Temic G6TK23AH54	68HC912D60A
BMW	Z3	G3T0C01AS73 Temic	68HC912B32
BMW	Z3	G4TOE08AD7 Temic	68HC912B32
 <h3 style="margin: 0;">CHEVROLET</h3>			
Chevrolet	Cavalier	22 674 098	68HC908AS20
Chevrolet	Aveo	96 442 703 Siemens 5WY67033	95160
 <h3 style="margin: 0;">CHRYSLER</h3>			
Chrysler	Voyager	0 285 001 093 Bosch 4686242	68HC11E9



Auto Consulting

		CITROËN	
Citroen		602 23 71 00	95080
Citroen		96 335 041 80 AL Autoliv 550 74 11 00	93C66
Citroen		96 390 154 80 Autoliv 550 74 09 00	93C66
Citroen	Berlingo	602 32 76 00 Autoliv 96 489 388 80	95080
Citroen	Berlingo	603 60 25 00 Autoliv 96 531 908 80 AC	95080
Citroen	Berlingo	96 371 768 00 Autoliv 550 74 83 00	93C66
Citroen	Berlingo	96 386 042 80 Autoliv 550 89 72 00	93C66
Citroen	C2	96 490 035 80 Temic	68HC912B32
Citroen	C2	96 608 551 80 Temic	95160
Citroen	C3	96 608 550 80 Temic	95160
Citroen	C3	96 477 942 80 Temic	68HC912B32
Citroen	C3	96 477 941 80 Temic	68HC912B32
Citroen	C3	96 490 035 80 Temic	68HC912B32
Citroen	C3	96 519 275 80 Temic	68HC912B32
Citroen	C3	96 568 887 80 Temic	68HC912B32
Citroen	C3	96 568 888 80 Temic	68HC912B32
Citroen	C3	96 568 890 80 Temic	68HC912B32
Citroen	C3	96 583 166 80 Temic	68HC912B32
Citroen	C3	96 607 316 80 Temic	95160
Citroen	C3	96 607 317 80 Temic	95160
Citroen	C3	96 609 611 80 Temic	95160
Citroen	C3	96 615 324 80 Temic	95160
Citroen	C4	603 72 61 00	95320
Citroen	C4	603 72 58 00	95320
Citroen	C5	96 419 683 80	68HC912B32
Citroen	C5	95 484 031 80	68HC912B32
Citroen	C5	96 486 655 80	68HC912B32
Citroen	C8	1 496 580 80 Temic	68HC912B32
Citroen	Jumper	13 284 470 80 5WK43154	95080
Citroen	Saxo	96 385 886 80 AK Autoliv 550 74 08 00	93C66

Auto Consulting

Citroen	Saxo	96 467 575 80 AQ Autoliv 550 89 29 00	95080
Citroen	Saxo	96 287 578 80 AT Autoliv 550 54 01 00	68HC11E9
Citroen	Saxo	96 345 647 80 Autoliv 550 57 96 00	93C66
Citroen	Xantia	96 335 043 80 Autoliv 550 74 09 00	93C66
Citroen	Xantia	96 336 213 80 Autoliv 550 53 53 00	93C66
Citroen	Xantia	96 225 857 80 Autoliv 550 40 25 00	68HC11E9
Citroen	Xantia	96 371 698 80 Autoliv 550 74 09 00	93C66
Citroen	Xsara	96 458 839 80 Autoliv 600 23 76 00	95080
Citroen	Xsara	96 389 42 80 Autoliv 550 74 11 00	93C66
Citroen	Xsara	96 225 858 80 Autoliv 550 51 93 00	93C66
Citroen	Xsara	96 464 690 80 AF 600 23 75 00 Autoliv	95080
Citroen	Xsara	96 319 506 80 Autoliv 550 53 89 00	68HC11E9
Citroen	Xsara	96 336 213 80 AN Autoliv 550 53 53 00	93C66
Citroen	Xsara	96 464 690 80 AF Autoliv 600 23 75 00	95080
Citroen	Xsara	96 464 691 80 AG Autoliv 600 23 76 00	95080
Citroen	Xsara	96 429 277 80 AM Autoliv 600 23 74 00	95080
Citroen	Xsara	96 429 278 80 Autoliv 600 23 73 00	95080
Citroen	Xsara	96 522 769 80 AJ Autoliv 602 32 74 00	95080
Citroen	Xsara Picasso	96 321 677 80 AT Autoliv 550 77 63 00	93C66
Citroen	Xsara Picasso	96 467 575 80 AO Autoliv 550 89 31 00	95080
 <h3 style="margin: 0;">DACIA</h3>			
Dacia	Logan	8200 702 320 Temic 403244A8	95160
Dacia	Logan	8200 307 188 Bosch 0 285 001 650	68HC912B32
 <h3 style="margin: 0;">DAEWOO</h3>			
Daewoo	Kalos	96 534 481	68HC11E20
Daewoo	Lanos	96 217 003 Siemens 5WK4155	68HC05B16
Daewoo	Lanos	96 220 439 7088107	68HC05B16
Daewoo	Lanos	96 314 931 7088110	68HC05B16

Auto Consulting

Daewoo	Lanos	96 387 637 Siemens 5WK43064	68HC11E20
Daewoo	Leganza	96 225 913	68HC11E9
Daewoo	Matiz	96 314 932 Siemens 5WK 4202	68HC05B16
Daewoo	Matiz	96 603 737	68HC11E20
Daewoo	Matiz	96 336 886	68HC05B16
 <h3 style="margin: 0;">DAIHATSU</h3>			
Daihatsu	Terios	89170-87428 Denso 152300-7190	93C56
Daihatsu	Sirion	89170-97202 Denso 152300-2023 DP	93C46
Daihatsu	Sirion	89170-97403 Denso 152300-4400	93C56
Daihatsu	Sirion	89170-97407 Denso 152300-4550	93C56
 <h3 style="margin: 0;">FIAT</h3>			
Fiat		46768868 Siemens 5WK42811	68HC05B16
Fiat		464793645 Hitachi	93C46
Fiat		13284470.80	95080
Fiat		46409123	
Fiat		51795431	25LC320
Fiat		51701716	25LC320
Fiat		51716748	
Fiat		51796381	25LC320
Fiat		60678004	24C04
Fiat	Brava	46413633	M951G
Fiat	Brava	46513525 5WK42817 Siemens	68HC11E20
Fiat	Brava	46538652 5WK42819 Siemens	68HC11E20
Fiat	Brava	46541774 Breed 5WK42811 Siemens	68HC05B16
Fiat	Brava	46541775 Breed 5WK42816 Siemens	68HC11E20
Fiat	Bravo	464793640	93C46
Fiat	Bravo	46550647 TRW	68HC908AZ60
Fiat	Bravo	46768868 Siemens 5WK42811	68HC05B16
Fiat	Bravo	46768869 5WK42816	68HC11E20


Auto Consulting

Fiat	Coupè	46306172	93C06
Fiat	Croma	51746149 TRW	25LC320
Fiat	Doblò	550 90 34 00 Autoliv	ST95080
Fiat	Doblò	550 90 35 00 Autoliv	ST95080
Fiat	Doblò	550 92 15 00 Autoliv	ST95080
Fiat	Doblò	607 14 16 00 Autoliv	95160
Fiat	Doblò	608 67 36 00 Autoliv 51772803 AE	95160
Fiat	Ducato	5WK43154 Siemens	95080
Fiat	Ducato	13169770.80 Breed	93C06
Fiat	Ducato	13231490.80 Breed	98HC11E20
Fiat	Ducato	5WK43155 Siemens 13284480.80	95080
Fiat	Grande Punto	51701716 TRW	25LC320
Fiat	Grande Punto	51795433 TRW	25LC320
Fiat	Grande Punto	51754872 TRW	25LC320
Fiat	Idea	51752039 TRW	95160
Fiat	Idea	51752040 TRW	95160
Fiat	Idea	51734430 TRW	95160
Fiat	Idea	51765169 TRW	95160
Fiat	Idea	51765170 TRW	25160
Fiat	Idea	51783815 TRW	25LC320
Fiat	Idea	51783816 TRW	25LC320
Fiat	Marea	46409123 Allied Signal	68HC11E9
Fiat	Marea	46538652 5WK 42819	68HC11E20
Fiat	Marea	46763600	68HC908AB32
Fiat	Marea	46550647	68HC908AS20
Fiat	Marea	46770172 Breed 5WK42819 Siemens	68HC11E20
Fiat	Marea	46789398	68HC908AS20
Fiat	Marea	46811840 TRW	68HC08AS32
Fiat	Palio	46409123	68HC11E9
Fiat	Palio	46443203 TRW	68HC11E9
Fiat	Palio	46529745	68HC11KS4
Fiat	Palio	51718980 TRW	24LC04
Fiat	Panda	46807549 331271	24C08

Auto Consulting

Fiat	Panda	46807549 TRW	24C08
Fiat	Panda	46807550 TRW	24LC04
Fiat	Panda	51778263 TRW	24LC08
Fiat	Panda	51803610 TRW	24LC08
Fiat	Punto I	46426776	93C06
Fiat	Punto I	46430655 TRW	68HC11E20
Fiat	Punto I	46517272 TRW	68HC11KA4
Fiat	Punto II	46758762 TRW	24LC04
Fiat	Punto II	46805905 TRW	24LC04
Fiat	Punto II	46766385	24LC04
Fiat	Punto II	46768868 Siemens 5WK42811	68HC05B16
Fiat	Punto II	46806592 TRW	24LC04
Fiat	Punto II	46766384 TRW	24LC04
Fiat	Punto II	46772034 TRW	24LC04
Fiat	Punto II	46806593 TRW	24LC04
Fiat	Punto II	46815442 TRW	24LC04
Fiat	Punto II	46806594 TRW	24LC04
Fiat	Punto III	51726575 331396 TRW	24LC04
Fiat	Punto III	51719091 331373	24LC04
Fiat	Punto III	51719092 331374	24LC04
Fiat	Scudo	550 54 00 00 Autoliv	68HC11E9
Fiat	Scudo	14893060.80	95080
Fiat	Scudo	14945330.80	95080
Fiat	Scudo	550 90 42 00 Autoliv	95080
Fiat	Seicento	46552426 TRW	68HC11KS4
Fiat	Seicento	46765423 TRW	68HC11KS4
Fiat	Seicento	46782817 TRW	24C04
Fiat	Seicento	51719095 TRW	24C04
Fiat	Stilo	46835521 5WK42969	95080
Fiat	Stilo	1000313 5WK43341	95080
Fiat	Stilo	51711815 5WK43341	95080
Fiat	Stilo	51711816 5WK43342	95080
Fiat	Stilo	51709144 5WK43346	95080


Auto Consulting

Fiat	Stilo	46835522 5WK43162	95080
Fiat	Stilo	51717959 5WK43343	95080
Fiat	Ulysse	14893060.80	95080
Fiat	Ulysse	14810020.80	68HC11E9
 <h1 style="color: blue; font-family: sans-serif;">FORD</h1>			
Ford		2T1T14B321AB 0285001417	68HC912D60 - 68HC912BE32
Ford		YS4T 14B056 CA Siemens 5WK 43103	95160
Ford	C-Max	0 285 001 452 Bosch 3M5T 14B056 BG	95080
Ford	C-Max	0 285 001 551 Bosch 4M5T 14B056 AD	95080
Ford	C-Max	0 285 001 847 Bosch 4M5T 14B056 AE	95080
Ford	Escape Truck	5L84 14B321 DE	95160
Ford	Escort	94AG 14B056 BA	68HC11E9
Ford	Escort	97AG 14B056 DA	68HC11E9
Ford	Escort	97AG 14B056 DB	68HC11E9
Ford	Escort	95AG 14B056 CD	68HC11E9
Ford	Fiesta	97FG 14B056 DF FIESTA PUMA97.5	68HC11E9
Ford	Fiesta	0 285 001 392 YS6T 14B056 AD	68HC912B32
Ford	Fiesta	0 285 001 393 YS6T 14B056 BD	68HC912B32
Ford	Fiesta	5S6T 14B056 HA 5WK43577	95160
Ford	Fiesta	2S6T 14B056 BP Siemens 5WK43030	95160
Ford	Fiesta	2S6T 14B056 EK Siemens 5WK43103	95160
Ford	Fiesta	6S6T 14B056 KC Siemens 5WK43586	95160
Ford	Fiesta	2S65 14B056 EP Siemens 5WK43103	95160
Ford	Fiesta	2S65 14B056 EN Siemens 5WK43103	95160
Ford	Fiesta	5S6T 14B056 HA Siemens 5WK43577	95160
Ford	Focus	0 285 001 394 Bosch YS4T 14B056 AA	68HC912B32
Ford	Focus	0 285 001 395 Bosch	68HC912B32
Ford	Focus	0 285 001 396 Bosch	68HC912B32
Ford	Focus	0 285 001 424 Bosch 2M5T 14B056 BE	68HC912D60
Ford	Focus	0 285 001 425 Bosch	68HC912D60
Ford	Focus	0 285 001 426 Bosch 2M5T-14B056-AD	68HC912D60

Auto Consulting

Ford	Focus	0 285 001 552 Bosch 4M5T 14B056 BJ	95080
Ford	Focus	0 285 001 551 Bosch 4M5T-14B056-AD	95080
Ford	Fusion	2S6T 14B056 BN Siemens 5WK43030	95160
Ford	Fusion	6S6T 14B056 LA Siemens 5WK43587	95160
Ford	Galaxy	1J0 909 603AA	68HC11E9
Ford	KA	3S5T 14B056 CB	68HC912B32
Ford	KA	0 285 001 398 Bosch YS5T 14B056 CA	68HC912B32
Ford	KA	0 285 001 399 Bosch YS5T 14B056 DA	68HC912B32
Ford	KA	0 285 001 494 Bosch 3S5T 14B056 AA	68HC912B32
Ford	Mondeo	3S7T 14B056 AB Visteon	95160
Ford	Mondeo	97BG 14B056 DD MONDEO97	68HC11E20
Ford	Mondeo	97BP 14B056 AAG	
Ford	Mondeo	603 95 10 00 Autoliv 4S7T 14B056 AB	95160
Ford	Mondeo	603 71 87 00 Autoliv 4S7T 14B056 AA	95160
Ford	Ranger	33210 Naldec SAS UH81 57 K30 A	24LC04
Ford	S-Max	0 285 010 140 Bosch 6M2T 14B056 AD	95160
	Tranzit Conect	0 285 001 417 Bosch	68HC912BE32
 HYUNDAI			
Hyundai		95910 3C200	68HC11E9
Hyundai	Accent	95910 25600 Siemens 5WK42932	95080
Hyundai	Accent	95910 25200 Siemens 5WK42928	68HC05B16
Hyundai	Accent	95910 25300 Siemens 5WK42929	68HC05B16
Hyundai	Accent	95910 25500 Siemens 5WK42931	95080
Hyundai	Accent	95910 25800 Siemens 5WK43070	95080
Hyundai	Atos	95910-02000	68HC05B16
Hyundai	Atos	95910-05600	68HC05B16
Hyundai	Atos	95910-05700	68HC05B16
Hyundai	Coupè	95910 2C100	68HC11E20
Hyundai	Coupè	95910 2C200	68HC11E9
Hyundai	Coupè	95910-2C500	MC9S12DG128
Hyundai	Elantra	95910-2D700	68HC08AS32

Auto Consulting

Hyundai	Elantra	95910-29950 Siemens 5WK4289	68HC05B16
Hyundai	Getz	95910 1C000 TRW	24LC04
Hyundai	Getz	95910 1C600 Mobis	24LC04
Hyundai	Matrix	95910-17600 Delphi 12210199	68HC08AS32
Hyundai	Santa Fe	95910-26600 Siemens 5WK43044	68HC05B16
Hyundai	Sonata	95910 3D200 Siemens 5WK43067	95080
Hyundai	Sonata	95910 39900 Siemens 5WK43215	95080
Hyundai	Terracan	95910-H1200 Sungwoo	68HC11E20
Hyundai	Tiburon	95910-2C200	68HC11E20
Hyundai	Tiburon	95910-27000 Siemens 5WK4172	68HC05B16
Hyundai	Trajet	95910 3A100	68HC11E20
Hyundai	Tuscon	95910-2E000 Bosch Delphi	9S12DG128
Hyundai	Tuscon	95910-2E100 Bosch Delphi	9S12DG128
Hyundai	Tuscon	95910-2E400 Bosch Delph	9S12DG128
	Tuscon	95910-2E700 Bosch Delphi	9S12DG128
HONDA			
Honda		77960-SN7-H91 Siemens 5WK4135	68HC05B16
Honda		77960-S04-G81 NEC	
Honda		77960-S04-G91	93C46
Honda		77960-S04-N91-M2	93C46
Honda		77960-S04-N93-M2	93C46
Honda		77960-S9A-Y414-M1	25320
Honda		77960-S10-G92	24C01
Honda		77960-S30-G81 NEC	24C01
Honda		77960-SFJ-W710-M2	93C66
Honda	CRX	77960-S10-G81 NEC	24C01
Honda	Accord	77960-SDN-A820-M1 TRW	25320
Honda	Accord	77960-SV4-A95-M2	24C01
Honda	Accord	77960-SDA-A620-M2 Denso	93C66
Honda	Accord	77960-SEA-G817-M1 TRW	25320
Honda	Accord	77960-SEA-G820-M1 TRW	25320


Auto Consulting

Honda	Accord	77960-SEF-G821-M1 TRW	25320
Honda	Accord	77960-SN7-G81 NEC	93C46
Honda	Civic	77960-SMG-E013-M1 TRW	95640
Honda	Civic	77960-SMR-G011-M1 TRW	95640
Honda	Civic	77960-SMG-G021-M1 TRW	95640
Honda	Civic	77960-SNA-A219-M1	95640
Honda	Civic	77960-SNB-G215-M1 TRW	95640
Honda	Civic	77960-SNB-T014-M1 TRW	95640
Honda	Civic	77960-SNB-T015-M1 TRW	95640
Honda	Civic	77960-SQ2-G81-M1	24C01
Honda	Civic	77960-SR3-L81 NEC	93C46
Honda	Civic	77960-ST3-E83 Siemens 5WK4136	68HC05B16
Honda	Civic	77960-SVA-A211-M1	95640
	CRV	77960-S10-A92	24C01
IVECO			
		504020907	24LC04
JAGUAR			
		1X4A 14B321 CG X400 Visteon	95080
KIA			
Kia	Carnival II	OK53677FOA	68HC11KS4
Kia	Picanto	95910-07200 Mobis	25320
Kia	Sephia II	OK2AA677F0B	68HC11KS4
	Sorento	95910-3E060 Siemens 5WY67056	95160
LANCIA			
Lancia		46544451 MC68HC08AS20	68HC08AS20
Lancia		46790521 MC68HC08AS20	68HC08AS20





Auto Consulting

Lancia		46790522 MC68HC08AS20	68HC08AS20
Lancia		46807478 MC68HC908AS60	68HC908AS60
Lancia		46812357 MC60HC908AS60	68HC908AS60
Lancia		46842735 EEPROM 93C66	93C66
Lancia		AUTOLIV 550 53 98 00	
Lancia	Lybra	46810798	68HC908AS60
Lancia	Kappa	500321296	68HC11KS4
Lancia	Lybra	46769379	68HC08AS20
Lancia	Musa	51783814 TRW 391134	25LC320
Lancia	Phedra	1 495 658 080 Temic	68HC912B32
Lancia	Y	601 45 80 00 Autoliv	95160
Lancia	Y	603 458 01 00 AG Autoliv	95160
	Y	46807479	68HC908AS32
 <h3 style="color: blue; margin: 0;">LAND ROVER</h3>			
Land Rover	Freelander	YWC000610 Siemens 5WK43117	93C66
Land Rover	Freelander	YWC105790 Autoliv	95080
Land Rover	Freelander	YWC106360 Autoliv	93C66
Land Rover	Freelander	YWC000610 Siemens 5WK43117	95080
	Range Rover	01-01724-00 B TRW 4905	68HC05B6
 <h3 style="color: blue; margin: 0;">LEXUS</h3>			
		0 285 001 903 Bosch 89170-53100 Toyota	95160
 <h3 style="color: blue; margin: 0;">MAZDA</h3>			
Mazda	6	GJ6A 57 K30 A 2G04B Visteon 33262 47	M95080
Mazda	6	GJ6A 57 K30 C	M95080
Mazda	626	GE4T 57 K30 D Ford	68HC11E9
Mazda	3	0 285 001 453 Bosch BP4 K57 K30 B	95080
Mazda	3	0 285 001 554 Bosch BP4 K57 K30 C	95080

Auto Consulting

Mazda	3	0 285 001 553 Bosch BP4 M57 K30	95080
Mazda	MX5	33212 45	24LC04
Mazda	MX5	33212 46	24LC04
Mazda	MX5	33212 50 Naldec	24LC04
Mazda	Premacy	33260 49 Naldec	24LC04
	RX8	SAS FE0157K30A Visteon 3327745	95080
 MERCEDES-BENZ			
Mercedes		0 285 001 077 Bosch 000 820 71 26	93C06
Mercedes		0 285 001 078 Bosch 000 820 72 26	93C06
Mercedes		0 285 001 030 Bosch 004 820 17 10	93C06
Mercedes		004 820 18 10 Bosch 0285001031	93C06
Mercedes		002 820 21 26(81) Temic	68HC912B32
Mercedes		0 285 001 031 MB 004 820 18 10 [08]	93C06
Mercedes		8207226	93C06
Mercedes		0 285 001 546 Bosch	CR16MCS9
Mercedes	C	0 285 001 373 Bosch 001 820 97 26	68HC12B32
Mercedes	C	001 820 21 26(04) Temic	68HC11KA4
Mercedes	C	0 285 001 165	68HC11K4
Mercedes	C	0 285 001 213 Bosch	68HC11E20
Mercedes	C	0 285 001 548 Bosch	CR16MCT9V
Mercedes	C	0 285 001 813 Bosch	CR16MCT9V
Mercedes	C	0 285 001 881 Bosch	CR16MCT9V
Mercedes	A	0 285 001 222 Bosch 001 820 31 261	68HC11K4
Mercedes	A	A1698206726 TRW	95320
Mercedes	Sprinter	0 285 001 105 Bosch ARS2 000 446 02 42 [00]	68HC11E9
Mercedes	Sprinter, Vito	0 285 001 477	68HC11E20
Mercedes	E	0 285 001 441 Bosch	CR16MCT9
Mercedes	E	001 820 00 26(01) Temic	68HC11KA4
Mercedes	E	001 820 00 26(11) Temic	68HC11KA4
	E	002 820 32 26(97) Temic	68HC912B32

Auto Consulting

 MINI			
Mini	Cooper	0 285 001 430	68HC912D60
	One	0 285 001 682	68HC912D60
 MITSUBISHI			
Mitsubishi		0 285 001 379	68HC912B32
Mitsubishi	Carisma	0 285 001 127 MR158433	68HC11E9
Mitsubishi	Carisma	0 285 001 232 MR309212 DPSB	68HC11KA4
Mitsubishi	Carisma	0 285 001 286 MR913789 DPB	68HC912
Mitsubishi	Carisma	0 285 001 235	68HC11E20
Mitsubishi	Carisma	0 285 001 290	68HC912BE32
Mitsubishi	Colt	0 285 001 684 Bosch MR587416	MC9S12D64
Mitsubishi	Colt	0 285 001 686 Bosch MR587416	MC9S12D64
Mitsubishi	Galant	MR309232 DPS X6T4208	93C56
Mitsubishi	L200/Strada	MR530002 DP Denso X6T41781	93C56
Mitsubishi	Lancer	MN141 261 DPSBC W2T62175	93C76
Mitsubishi	Pajero	152300 2461 Denso MR268156	93C46
Mitsubishi	Pajero	152300 2471 Denso MR268157 DP	93C46
Mitsubishi	Pajero	152300 3430 Denso MR472773 DP	93C56
Mitsubishi	Pajero	152300 1052 Denso MR268157 DP	93C46
Mitsubishi	Pajero	152300 3460 Denso MR472776	93C56
Mitsubishi	Pajero	MR587868	93C56
Mitsubishi	Spacestar	0 285 001 379 Bosch MR912128 DPSB	68HC912B32
	Spacestar	0 285 001 244 Bosch MR318 479 DPSB	68HC11K4
 NISSAN			
Nissan		0 285 001 639 Bosch 98820 BU900	68HC12BE32
Nissan		0 285 001 188 Bosch 28556 2F400	68HC11E9
Nissan		0 285 001 193 Bosch	68HC711E9

Auto Consulting

Nissan		0 285 001 319 Bosch 98820 5M304 J	68HC912B32
Nissan		28556 43U00	93C46
Nissan		28556 43U01	68HC11E9
Nissan		28556 8Z800	93C56
Nissan		98820 9H606	93C56
Nissan	200SX	28556 82F05	68HC11E9
Nissan	350Z	98820 CD600	
Nissan	Almera	28556 3N705	93C56
Nissan	Almera	98820 2N400 D	93C56
Nissan	Almera	98820 3L300 G	93C56
Nissan	Almera	0 285 001 316 Bosch 28556 5M301 G	68HC12B32
Nissan	Almera	0 285 001 319 Bosch 98820 5M304 J	68HC12B32
Nissan	Almera	0 285 001 638 Bosch 98820 BN902 R	68HC12B32
Nissan	Maxima	28556 41U00	93C46
Nissan	Maxima	98820 1L270	93C56
Nissan	Micra	0 285 001 182 Bosch 28556 6F605	68HC11E20
Nissan	Micra	0 285 001 411 Bosch 28556 AP002 M	68HC912B32
Nissan	Micra	0 285 001 311 Bosch	68HC912B32
Nissan	Micra	0 285 001 413 Bosch 98820 AP003 X	68HC912B32
Nissan	Micra	0 285 001 853 98820 BC500	24C08
Nissan	Navarra	28556 2S700	93C46
Nissan	Note	0 285 001 907 Bosch 28556 1U70A	24C08
Nissan	Note	0 285 001 909 Bosch	24C08
Nissan	Pathfinder	98820 5W915	93C56
Nissan	Pick Up	28556 2S700	93C46
Nissan	Pick Up Skystar	28556 VJ200	93C56
Nissan	Primera	0 285 001 194 Bosch	68HC11E9
Nissan	Primera	0 285 001 323 Bosch 28556 74B02 D	68HC912B32
Nissan	Primera	0 285 001 327 Bosch 28556 7J600 6	68HC912B32
Nissan	Primera	0 285 001 329 Bosch 98820 7J700 7	68HC912B32
Nissan	Primera	0 285 001 420 Bosch 98820 AV200	68HC912B32
Nissan	Teana	28556 9W100	93C56
Nissan	Teana	98820 9Y60E1	93C56

Auto Consulting

Nissan	Terrano	0 285 001 186 Bosch 28556 8F200	68HC11E20
Nissan	Terrano	0 285 001 137 Bosch 28556 7F001	68HC11E9
Nissan	Terrano	0 285 001 481 Bosch	68HC12BE32
Nissan	Vanette	0 285 001 195	68HC711E9
Nissan	X-Trail		93C56
Nissan	X-Trail	988208H405	93C56
Nissan	X-Trail	98820 9H600	93C56
	X-Trail	98820 9H605	93C56
 OPEL			
<u>Opel</u>		09 114 585 EE	68HC11E9
Opel		1J0 609 607	
Opel		9216732 5WK43458	95080
Opel		09 174 006 UW 5WK42878	68HC08AZ32
Opel		09 180 800 TY	68HC11E9
Opel		09 229 239 BD	
Opel		24 466 287 temic	68HC908AZ60
Opel		90 492 467 LJ 5WK 4110	68HC05B6
Opel		90 508 980 5WK 4169	68HC05B16
Opel		90 483 546 LP	68HC05B6
Opel		90 532 629 BG 5WK 4115A	68HC05B6
Opel	Tigra	09 114 586 EF 5WK41150B	68HC11E9
Opel	Agila	38910-83E01-000 5WK42898	68HC11E20
Opel	Agila	38910-83E02-000 5WK42898	68HC11E20
Opel	Agila	38910-83E11-000 5WK42897	68HC11E20
Opel	Agila	38910-84E20-000 5WK43459	
Opel	Astra	09 174 004 UU 5WK42876	68HC08AZ32
Opel	Astra	24 407 210 5WK4298	68HC08AZ32
Opel	Astra	24 417 007 Temic	68HC08AZ32
Opel	Astra	90 450 273 JP Siemens 5WK4072	68HC05B6
Opel	Astra	09 229 302 BF Siemens 5WK42925	68HC08AZ32A or 68HC08AZ32
Opel	Astra G	24 416 703 DL 5WK42977	68HC908AZ32

Auto Consulting

Opel	Astra G	24 416 703 BF 5WK42977	68HC908AZ32
Opel	Astra G/Corsa C	24 439 954 Temic	68HC08AZ32
Opel	Astra G/Vectra B	09 229 037 BC 5WK42923	68HC11E9
Opel	Astra G/Zafira	24 416 704 DM 5WK42978	68HC08AZ32
Opel	Astra H	13 188 854 GS Temic	M9S12DG128E
Opel	Astra H	13 188 855 Temic	M9S12DG128E
Opel	Astra H	13 188 857 Temic	M9S12DG128E
Opel	Astra H	13 191 825 Temic	M9S12DG128E
Opel	Astra H	13 227 920 Temic	M9S12DG128E
Opel	Astra/Vectra B	09 180 799 UY 5WK42905	68HC11E9
Opel	Astra/Vectra B	90 520 841 AF Siemens 5WK4168	68HC11E9
Opel	Astra/Vectra B	90 532 443 AG Siemens 5WK4189	68HC11E9
Opel	Combo C	24 417 008 DT Temic	68HC908AZ32
Opel	Corsa	13 212 353 Temic	68HC08AZ32
Opel	Corsa	90 532 628 BF (or BJ or EE) Siemens 5WK4114	68HC05B6
Opel	Corsa B	09 229 038 BB 5WK42924	68HC11E9
Opel	Corsa B	09 229 038 BB BBS057713U 5WK42924	68HC11E9
Opel	Corsa B	09 229 039 BD 5WK42922	68HC11E9
Opel	Corsa B	24 416 692 DH 5WK42976	68HC11E9
Opel	Corsa B	90 483 545 LN 5WK4114	68HC05B6
Opel	Corsa C	24 417 006 DR Temic	68HC08AZ32
Opel	Corsa C	24 417 007 DS Temic	68HC08AZ32
Opel	Corsa C	24 423 840 EP Temic	68HC908AZ60
Opel	Corsa C	24 439 952 LA Temic	68HC08AZ32
Opel	Corsa C	24 439 953 LB Temic	68HC08AZ32
Opel	Corsa C	24 439 954 LC Temic	68HC08AZ32
Opel	Corsa C	24 439 959 Temic	68HC08AZ32
Opel	Meriva	13 158 712 ZJ Temic	68HC908AZ32
Opel	Meriva	13 158 713 ZK Temic	68HC908AZ32
Opel	Meriva	13 203 620 Temic	68HC08AZ32
Opel	Movano	550 75 21 00 Autoliv	93C66
Opel	Omega	90 562 544 BJ 5WK4113A	68HC05B6
Opel	Omega	90 565 938 DC	68HC11E9

Auto Consulting

Opel	Omega B	90 481 747 KG	68HC05B6
Opel	Omega B	90 491 004 KJ	68HC05B6
Opel	Omega B	90 519 067 LM 5WK 4113	68HC05B16
Opel	Sintra/Zafira	16210361 *361633100YB*	68HC11E9
Opel	Vectra B	09 180 801 UZ 5WK42903	68HC11E9
Opel	Vectra B	90 462 072 JM 5WK 4070	68HC05B6
Opel	Vectra B	90 464 705 AC	68HC11E9
Opel	Vectra B	90 569 340 BQ 5WK4175	68HC11E9
Opel	Vectra B	90 569 350 DB 5WK4188	68HC11E9
Opel	Vectra C	13 102 021 Siemens 5WK43262	95160
Opel	Vectra C	12 102 022 Siemens 5WK43261	95160
Opel	Vectra C	13 142 540 Delco	68HC912D60 & 95040
Opel	Vectra C	13 118 804 AQ TRW	68HC912D60 & 95040
Opel	Vectra C	13 129 843 CL TRW	68HC12D60 & 95040
Opel	Vectra C	13 142 540 GP TRW	68HC12D60 & 95040
Opel	Vectra C	13 159 975 Siemens	95160
Opel	Vectra C	13 159 977 Siemens	95160
Opel	Vectra C	13 170 589 Siemens 5WK43471	95160
Opel	Vectra C	13 181 977 Temic	M9S12DG128E
Opel	Vivaro	602 86 92 00 Autoliv	95160
Opel	Vivaro	605 48 80 00 Autoliv 8200 435 346A	95160
Opel	Zafira	13 188 856 Temic	M9S12DG128E
Opel	Zafira	09 229 303 BG 5WK42926	68HC08AZ32
Opel	Zafira	90 582 536 DG 5WK4190	68HC11E9
 <h1 style="color: blue; font-family: sans-serif;">PEUGEOT</h1>			
Peugeot		550 54 00 00 Autoliv	68HC11E9
Peugeot		9628757880 Autoliv 550540100	68HC11E9
Peugeot		9641728780 Autoliv 600 279 100	93C46
Peugeot		Autoliv 550 751 800	93C66
Peugeot		550 58 14 00 Autoliv 96 374 919 80 AP	93C56
Peugeot	106	550 53 85 00 Autoliv 96 287 575 80 AJ	68HC11E9





Auto Consulting

Peugeot	106	550 53 84 00 Autoliv 96 287 576 80	68HC11E9
Peugeot	106	550 53 84 00 Autoliv 96 287 576 80 AH	68HC11E9
Peugeot	106	550 53 84 00 Autoliv 96 287 576 80 AJ	68HC11E9
Peugeot	106	550 57 91 00 Autoliv 96 305 513 80 AH	93C66
Peugeot	106	550 79 04 00 Autoliv 96 385 887 80 AC	93C66
Peugeot	106	550 89 28 00 Autoliv (96 399 173 80 AJ & 96 467 573 80)	95080
Peugeot	106	550 89 27 00 Autoliv 96 412 487 80 AI	95080
Peugeot	106	550 53 85 00	68HC711E9
Peugeot	106	550 74 74 00 Autoliv 96 350 026 80 AI	93C66
Peugeot	106	550 89 27 00 version 10	95080
Peugeot	206	550 54 15 00 Autoliv 96 352 688 80 AK	93C66
Peugeot	206	550 54 15 00 Autoliv 96 368 940 80 AR	93C66
Peugeot	206	550 54 15 00 Autoliv 96 368 940 80 AT	93C66
Peugeot	206	550 54 15 00 Autoliv 96 368 940 80 AX	93C66
Peugeot	206	550 54 15 00 Autoliv 96 368 940 80 AM	93C66
Peugeot	206	550 54 15 00 Autoliv 96 430 823 80 AY	93C66
Peugeot	206	550 54 15 00 Autoliv 96 430 823 80 AZ	93C66
Peugeot	206	550 66 10 00 Autoliv 96 434 004 80 AR	93C56
Peugeot	206	600 23 70 00 Autoliv 96 449 032 80 AC	95080
Peugeot	206	600 23 71 00 Autoliv 96 449 033 80 AC	95080
Peugeot	206	600 23 72 00 Autoliv 96 449 034 80	95080
Peugeot	206	602 32 73 00 Autoliv 96 522 759 80 AM	95080
Peugeot	206	602 32 70 00 Autoliv 96 501 366 80 AF	95080
Peugeot	206	602 32 71 00 Autoliv	95080
Peugeot	206	602 32 73 00 Autoliv	95080
Peugeot	206	603 20 10 00 Autoliv 96 534 418 80 AE	95080
Peugeot	206	603 20 12 00 Autoliv 96 534 419 80	95080
Peugeot	306	550 53 91 00 Autoliv 96 287 404 80 AH	68HC11E9
Peugeot	306	550 53 92 00	68HC11E9
Peugeot	306	550 54 15 00 Autoliv	93C66
Peugeot	306	550 58 95 00 Autoliv 96 320 51 80	93C56
Peugeot	306	550 57 81 00 Autoliv 96 336 211 80 AM	93C66
Peugeot	306	550 57 81 00 Autoliv 96 336 211 80 AQ	93C66

Auto Consulting

Peugeot	306	550 57 92 00 Autoliv 96 336 212 80 AN	93C66
Peugeot	306	550 74 10 00 Autoliv 96 368 941 80 AP	93C66
Peugeot	306	550 74 10 00 Autoliv 96 369 955 80	93C66
Peugeot	306	550 86 45 00 Autoliv	95080
Peugeot	307	601 95 82 00 Autoliv 96 523 638 80	95080
Peugeot	307	603 72 49 00 Autoliv 96 534 933 80	95320
Peugeot	307	606 87 73 00 Autoliv 96 544 911 80	95320
Peugeot	307	606 87 75 00 Autoliv 96 544 912 80	95320
Peugeot	307	96 357 842 80 Siemens 5WK42908	95080
Peugeot	307	96 407 229 80 Siemens 5WK42908	95080
Peugeot	307	96 501 094 80 Siemens 5WK42908	95080
Peugeot	307	96 501 092 80 Siemens 5WK42908	95080
Peugeot	307	96 527 121 80 Siemens	95080
Peugeot	405	550 72 52 00 Autoliv 96 385 925 80	93C66
Peugeot	406	550 53 96 00 Autoliv 96 287 570 80 AR	68HC11E9
Peugeot	406	550 53 95 00 Autoliv 96 287 571 80 AQ	68HC11E9
Peugeot	406	550 53 95 00 Autoliv 96 287 571 80 AR	68HC11E9
Peugeot	406	550 53 94 00 Autoliv 96 287 572 80 AQ	68HC11E9
Peugeot	406	550 53 75 00 Autoliv 96 305 507 80 AI	93C66
Peugeot	406	550 54 04 00 Autoliv 96 318 470 80	93C56
Peugeot	406	550 72 52 00 Autoliv 96 371 764 80 AG	93C66
Peugeot	406	550 72 52 00 Autoliv 96 385 925 80 AK	93C66
Peugeot	406	550 72 52 00 Autoliv 96 385 925 80 AM	93C66
Peugeot	406	600 90 28 00 Autoliv 96 458 502 80 AD	95080
Peugeot	406	550 39 39 00 Autoliv 96 503 939 00 AM	68HC11E9
Peugeot	406	550 39 40 00 Autoliv	68HC11E9
Peugeot	406	550 53 75 00 AH Autoliv	93C66
Peugeot	407	603 55 46 00 Autoliv	95320
Peugeot	407	603 60 26 00 Autoliv	95320
Peugeot	605	550 53 86 00 Autoliv 96 287 574 80 AQ	68HC11E9
Peugeot	607	603 48 20 00	95320
Peugeot	607	96 403 411 80 Temic	68HC11E20
Peugeot	607	96 438 697 80 Temic	68HC11E20

Auto Consulting

Peugeot	806	550 53 97 00 Autoliv 14 809 990 80 AT	68HC11E9
Peugeot	806	550 53 98 00 Autoliv 14 810 000 80 AR	68HC11E9
Peugeot	807	1499801080 Temic L4V4H28AGY	68HC912B32
Peugeot	Boxer	13 284 470 80 5WK43154	95080
Peugeot	Boxer	5WK43155	95080
	Partner	550 74 83 00 Autoliv 96 371 768 80 AC	93C66
	Partner	550 89 72 00 Autoliv 96 386 042 80 AX	93C66
 <h3 style="margin: 0;">PONTIAC</h3>			
	G6	15775352 GA	95160
	Vibe	89170-01020 Denso	25040
 <h3 style="margin: 0;">RENAULT</h3>			
Renault		Autoliv 550 473 800	68HC11E9
Renault		46768868 5WK42811	68HC05
Renault	Clio	0 285 001 155 Bosch	68HC11E20
Renault	Clio	0 285 001 156 Bosch 7700 434 205	68HC11E20
Renault	Clio	0 285 001 157 Bosch 7700 428 310G	68HC912BE32
Renault	Clio	0 285 001 312 Bosch 7700 428 311C	68HC912D60
Renault	Clio	0 285 001 414 Bosch	68HC912D60
Renault	Clio	0 285 001 415 Bosch 8 200 054 938	68HC912D60
Renault	Clio	0 285 001 537 Bosch 8 200 277 317	68HC912D60
Renault	Clio	0 285 001 496 Bosch 8 200 230 857	68HC912D60
Renault	Clio	0 285 001 958 Bosch 8200 645 158	95160
Renault	Clio	550 42 08 00 Autoliv	68HC11E9
Renault	Clio	0 285 001 510 Bosch 8200 563 368	95160
Renault	Clio	0 285 001 511 Bosch 8200 528 766	95160
Renault	Clio	0 285 001 538 Bosch 8200 277 318	68HC912D60
Renault	Espace	603 78 55 00 Autoliv 8200 313 338	95160
Renault	Espace	602 53 135 96D Breed Siemens 5WK41851	68HC11E20


Auto Consulting

Renault	Kangoo	600 63 94 00 Autoliv	95080
Renault	Kangoo	600 58 96 00 Autoliv 8200 098 402	93C66
Renault	Kangoo	602 62 92 00 Autoliv	95080
Renault	Kangoo	603 95 13 00 Autoliv 8200 314 053	95080
Renault	Kangoo	604 64 91 00 Autoliv 8200 354 723AA	95080
Renault	Kangoo	605 04 49 00 Autoliv	95080
Renault	Laguna	550 34 74 00 Autoliv	68HC11E9
Renault	Laguna	550 53 62 00 Autoliv	93C66
Renault	Laguna	550 75 87 00 Autoliv 8200 148 227A AC	95080
Renault	Laguna	550 75 88 00 Autoliv 8200 108 371AF	95080
Renault	Laguna	550 80 44 00 Autoliv	93C66
Renault	Laguna	601 95 88 00 Autoliv 8200 138 952	95080
Renault	Laguna	602 99 05 00 Autoliv	95160
Renault	Laguna	603 94 78 00 Autoliv	95160
Renault	Laguna	603 94 77 00 Autoliv 8200 325 696	95160
Renault	Laguna	603 94 77 00 Autoliv 8200 410 977	95160
Renault	Laguna	605 48 76 00 Autoliv	95160
Renault	Laguna	550 44 91 00 Autoliv	68HC11E9
Renault	Laguna	550 44 92 00 Autoliv 7700 414 215C	68HC11E9
Renault	Megane	600 63 94 00 Autoliv	95080
Renault	Megane	600 63 95 00 Autoliv 8200 117 652AJ	95080
Renault	Megane	600 63 96 00 Autoliv 8200 117 653A	95080
Renault	Megane	550 34 74 00 Autoliv	68HC11E9
Renault	Megane	550 34 75 00 Autoliv 7700 423 185A	68HC11E9
Renault	Megane	550 54 84 00 Autoliv 8200 101 440A	93C66
Renault	Megane	550 56 90 00 Autoliv	93C66
Renault	Megane	550 62 95 00 Autoliv	93C66
Renault	Megane	550 80 38 00 Autoliv 8200 111 672	93C66
Renault	Megane	603 88 07 00 Autoliv	95160
Renault	Megane	603 38 33 00 Autoliv	95160
Renault	Megane	603 38 37 00 Autoliv	95160
Renault	Megane	603 04 73 00 Autoliv 8200 280 991AH	95160
Renault	Megane	603 04 75 00 Autoliv 8200 280 994AH	95160




Auto Consulting

Renault	Megane	601 05 04 00 Autoliv 8200 246 184EAE	95160
Renault	Megane	601 05 50 00 Autoliv 8200 246 182F	95160
Renault	Megane	603 30 29 00 Autoliv	95160
Renault	Megane	603 98 90 00 Autoliv 8200 340 428	95160
Renault	Megane	603 98 99 00 Autoliv	95160
Renault	Megane	604 28 99 00 Autoliv 8200 481 129AA	95160
Renault	Megane	604 28 96 00 Autoliv	95160
Renault	Megane	604 28 97 00 Autoliv 8200 411 005A	95160
Renault	Megane	604 28 97 00 Autoliv 8200 367 445AC	95160
Renault	Megane	604 53 90 00 Autoliv 8200 481 132	95160
Renault	Megane	603 98 88 00 Autoliv	95160
Renault	Megane	605 48 99 00 Autoliv 8200 412 026	95160
Renault	Megane	605 48 99 00 Autoliv 8200 412 029B	95160
Renault	Megane	607 06 05 00 Autoliv	95160
Renault	Megane	607 13 93 00 Autoliv 8200 412 026	95160
Renault	Megane	770 437 476A Autoliv	93C66
Renault	Megane Coupe	550 54 84 00 Autoliv 7700 418 152F	93C66
Renault	Megane Coupe	550 80 36 00 Autoliv SW25	93C66
Renault	Megane Coupe	550 62 94 00 Autoliv 7700 430 059B	93C66
Renault	Megane Scenic	603 98 97 00 Autoliv 8200 411 013	95160
Renault	Modus	0 285 001 509 Bosch 8200 (441 250, 463 297,475 989, 533 970)	95160
Renault	Modus	0 285 001 817 Bosch 8200 505 719	95160
Renault	Scenic	550 50 99 00 Autoliv	68HC11E9
Renault	Scenic	550 56 90 00 Autoliv	93C66
Renault	Scenic	550 80 38 00 Autoliv	93C66
Renault	Scenic	600 63 95 00 Autoliv	95080
Renault	Scenic	603 98 97 00 Autoliv	95160
Renault	Scenic II	604 29 04 00 Autoliv 8200 375 209	95160
Renault	Thalia	0 285 001 157 Bosch 8200 335 427	68HC912B32
Renault	Traffic	550 79 07 00 Autoliv 8200 112 746	95080
Renault	Traffic	550 75 21 00 Autoliv 8200 098 404 AC	93C66
Renault	Traffic	601 95 98 00 Autoliv 8200 112 746A	95080
Renault	Traffic	602 86 92 00 Autoliv	95160

Auto Consulting

	Renault	Traffic	602 99 05 00 Autoliv 8200 285 627	95160
	Renault	Twingo	550 54 69 00 Autoliv	93C66
	Renault	Twingo	550 65 18 00 Autoliv	68HC11E9
	Renault	Twingo	550 65 39 00 Autoliv	93C66
	Renault	Twingo	550 80 48 00 Autoliv 8200 018 835A	93C66
		Twingo	550 88 53 00 Autoliv 8200 058 365E	95080
		Kangoo	550 75 18 00 Autoliv 8200 098 401AC	93C66
ROVER				
	Rover	200	YWC 105220	68HC11E1
	Rover	25	602 86 47 00 Autoliv YWC 001180	95080
	Rover	45	YWC 107010	68HC912B32
	Rover	75	602 86 49 00AF Autoliv YWC 001160	95080
	Rover	75	YWC 106790	68HC912B32
	Rover	400	YWC 105210	68HC11E1
		600	77960-SN3-G81	93C46
		MGF	YWC 105230	68HC11E9
SAAB				
		9-3	12762954	95320
		9-3	12802256	95320
SEAT				
	Seat	Alhambra	1J0 909 603 Siemens 5WK4163 VW3	68HC11E9
	Seat	Cordoba	1J0 909 603 BQ Siemens 5WK4163 VW3	68HC11E9
	Seat	Cordoba	6Q0 909 601AE TRW	24C08
	Seat	Cordoba	6Q0 909 601AD TRW	24C08
	Seat	Cordoba	6Q0 909 601E VW5 TRW	24C08
	Seat	Cordoba	6Q0 909 605R VW5 TRW	24C08
	Seat	Ibiza	6Q0 909 605F VW5 TRW	24C08

Auto Consulting

Seat	Ibiza	6Q0 909 605R VW5 TRW	24C08
Seat	Ibiza	6Q0 909 605S VW5 TRW	24C08
Seat	Ibiza	6Q0 909 605AD VW5 TRW	24C08
Seat	Ibiza	6Q0 909 605AE VW5 TRW	24C08
Seat	Ibiza	6Q0 909 605L VW5 TRW	24C08
Seat	Leon	1C0 909 605A Siemens	68HC08AZ32
Seat	Leon	3C0 909 605E TRW	25LC640
Seat	Leon	3C0 909 605H TRW	25LC640
Seat	Leon	3C0 909 605L TRW	25LC640
	Toledo	1K0 909 605H Siemens 5WK43411 VW8	95160
	Toledo	1K0 909 605C VW8	95160
SKODA			
Škoda	Fabia	6Q0 909 601 C Siemens VW5	68HC08AZ32
Škoda	Fabia	1C0 909 601C VW51	68HC
Škoda	Octavia	1C0 909 601 5WK43120 VW51	68HC
Škoda	Octavia	6Q0 909 605 Siemens 5WK42866	68HC08AZ32
Škoda	Octavia II	1K0 909 605 N Siemens	95160
	er B	1C0 909 605 H Siemens 5WK43127 VW51	
	er B	1C0 909 605 K Siemens 5WK43125 VW51	
SMART			
	Smart	Temic	MC68HC11KA4
SUZUKI			
Suzuki	Grand Vitara	38910-65D1 DPT Denso 152300-2043	93C46
Suzuki	Ignis	38910-80G20 Mitsubishi Electric	93C46
Suzuki	Ignis	38910-86G12-000 Siemens 5WK43395	95080
Suzuki	Jimny	38910-81A4 Mitsubishi	93C46
Suzuki	Jimny	38910-81AD0 Mitsubishi	93C46
Suzuki	Liana	38910-54G4 Siemens 5WK43036	68HC11E20

Auto Consulting

Suzuki	Swift	38910-62J00-000 Siemens 5WK43538	95160
Suzuki	Swift	38910-62J10-000 Siemens 5WK43539	95160
Suzuki	Swift	38910-62J11-000 Siemens 5WK43539	95160
	SX4	38910-79J20-000 Siemens 5WK43632	956160
TOYOTA	Wagon R+	38910-83E20-000 Siemens 5WK42899	68HC11E20
TOYOTA			
Toyota		89170-52170	93C56
Toyota		89170-12110	24C01
Toyota	Auris	89170-02110 TRW 215537-10	25040
Toyota	Avensis	89170-05030 TRW	25040
Toyota	Avensis	89170-05080 TRW	25040
Toyota	Avensis	89170-05121 TRW	25040
Toyota	Aygo	89170-0H040 TRW	95040
Toyota	Camry		93C56
Toyota	Carina	1032469E TRW 89170-05010D	68HC11KA4
Toyota	Celica	89170-20030 DP	24C01
Toyota	Corolla	89170-02180 TRW	25040
Toyota	Corolla	89170-02370 TRW	25040
Toyota	Corolla	89170-02380 TRW	25040
Toyota	Corolla	89170-02400 TRW	25040
Toyota	Corolla	89170-02600 TRW	25040
Toyota	Corolla	89170-12280	93C56
Toyota	Corolla	89170-12471	93C56
Toyota	Corolla	89170-13020	93C56
Toyota	Hi Ace	89170-12070 Fujitsu 231000-0620	24C01
Toyota	Hi Ace	89170-12080 Fujitsu 231000-0630	24C01
Toyota	Landcruiser	89170-60090	93C56
Toyota	Landcruiser	89170-60200	93C56
Toyota	Rav4	89170-42050	93C56
Toyota	Rav4	89170-42080 PT	93C56
Toyota	Rav4	89170-42090	93C56

Auto Consulting

Toyota	Yaris	89170 0D040 TRW	25040
Toyota	Yaris	89170-0D070 TRW	25040
Toyota	Yaris	89170 0D080 TRW	25040
Toyota	Yaris	89170 0D090 TRW	25040
Toyota	Yaris	89170-0D210 TRW 212986-103	25040
Toyota	Yaris	89170-0D250 TRW	25040
	Yaris	89170-52030 Fujitsu Ten	93C56
	Yaris	89170-52040 Fujitsu Ten	S220
VOLKSWAGEN			
Volkswagen		1J0 909 603 A VW3	68HC11E9
Volkswagen		1C0 909 601 Siemens 5WK43120 VW5	68HC08AZ32
Volkswagen		1C0 909 601 A Siemens W5	
Volkswagen		1J0 909 603 AC VW3	68HC11E9
Volkswagen		1J0 909 603 E VW3	68HC11E9
Volkswagen		1J0 909 603 5WK4163 VW3	68HC11E20
Volkswagen		1J0 909 604 A VW3	68HC11E9
Volkswagen		1J0 909 607 A VW3	68HC11
Volkswagen		1J0 909 608 5WK4154 VW3	68HC11E9
Volkswagen		1J0 909 608 AN Siemens 5WK4154 VW3	68HC11E9
Volkswagen		1J0 909 608 BA Siemens 5WK4154 VW3	68HC11E9
Volkswagen		1K0 909 605 H VW8	95160
Volkswagen		1K0 909 605 K 5WK43410 VW8	95160
Volkswagen		1K0 909 605 P Siemens 5WK43700	95160
Volkswagen		1K0 909 605 R VW8 5WK43412	95160
Volkswagen		1T0 909 605 B 5WK43518 VW62	68HC912D60
Volkswagen		3B0 959 655 B Bosch 0 285 001 173 VW3	68HC11E20
Volkswagen		3C0 909 605 J TRW VW8	25LC640
Volkswagen		6N0 909 601 E Siemens 5WK4104E	68HC05B16
Volkswagen		6N0 909 601 H Siemens 5WK4130 VW2	68HC05B16
Volkswagen		6N0 909 603 VW2	68HC05B16
Volkswagen		6N0 909 603 AC 5WK4137 VW2	68HC05B16

Auto Consulting

Volkswagen		6N0 909 603 AM VW2	68HC05B16
Volkswagen		6N0 909 603 AR 5WK4137 VW2	68HC05B16
Volkswagen		6N0 909 603 E VW2	68HC05B16
Volkswagen		6N0 909 603 F VW2	68HC05B16
Volkswagen		6N0 909 603 H VW2	68HC05B16
Volkswagen		6N0 909 603 P VW2	68HC05B16
Volkswagen		6N0 909 603 T VW2	68HC05B16
Volkswagen		6N0 909 606 E VW2	68HC05B16
Volkswagen		6N0 909 606 S VW2	68HC05B16
Volkswagen		6Q0 909 601 5WK42865 VW5	68HC08AZ32
Volkswagen		6Q0 909 601 A Siemens 5WK42868 VW5	68HC08AZ32
Volkswagen		6Q0 909 601 F TRW VW5	24C08
Volkswagen		6Q0 909 605 Siemens 5WK42866 VW5	68HC08AZ32
Volkswagen		6Q0 909 605 A Siemens 5WK42867 VW5	68HC08AZ32
Volkswagen		6Q0 909 605 B Siemens 5WK42869 VW5	68HC08AZ32
Volkswagen		6Q0 909 601 B TRW VW5	24C08
Volkswagen		8L0 959 655 A Bosch 0 285 001 174	68HC11K4
Volkswagen		8L0 959 655 B Bosch	68HC11K4
Volkswagen		6Q0 909 605 H Siemens 5WK42950 VW5	68HC08AZ32
Volkswagen	Golf IV	1J0 909 603 AN Siemens 5WK4163 VW3	68HC11E9
Volkswagen	Caddy	6Q0 909 605 P VW52	68HC08AZ32
Volkswagen	Caddy	6Q0 909 605 T VW52	68HC908AZ60A
Volkswagen	Golf IV	1C0 909 605 F VW61	68HC912
Volkswagen	Golf IV	1J0 909 609 A 5WK42800 VW3	68HC11E9
Volkswagen	Golf IV	1J0 909 609 VW3	68HC11
Volkswagen	Golf IV	6Q0 909 605 F	
Volkswagen	Golf V	1K0 909 605 A VW8	95160
Volkswagen	Golf V	1K0 909 605 C VW8	95160
Volkswagen	Golf V	1K0 909 605 D VW8	95160
Volkswagen	Golf V	1K0 909 605 E Siemens 5WK43415 VW8R	95160
Volkswagen	Golf V	1K0 909 605 N VW8	95160
Volkswagen	Golf V	1K0 909 605 T VW8 5WK43412	95160
Volkswagen	Jetta	1K0 909 605 L Siemens 5WK43410 VW8	95160

Auto Consulting

Volkswagen	New Beetle	6Q0 909 605 E	95320
Volkswagen	Passat	1C0 909 605 B 5WK43124 VW51	68HC908AZ32
Volkswagen	Passat	1C0 909 605 C VW61	68HC12D60
Volkswagen	Passat	1J0 909 607 5WK4199	68HC11E9
Volkswagen	Passat	1J0 909 607 C 5WK4199	68HC11E9
Volkswagen	Passat	1J0 909 607 XA Siemens	68HC11E9
Volkswagen	Passat	3C0 909 605 A TRW VW8	25LC640
Volkswagen	Passat	3C0 909 605 C TRW VW8	25LC640
Volkswagen	Passat	3C0 909 605 F TRW VW8	25LC640
Volkswagen	Passat	3C0 909 605 M TRW VW8	25LC640
Volkswagen	Polo	6N0 909 603 5WK4137 VW2 nekodiran	68HC05B16
Volkswagen	Polo	6N0 909 603 5WK4137 VW2	68HC05B16
Volkswagen	Polo	6Q0 909 601 E TRW VW5	24C08
Volkswagen	Polo	1C0 909 605 K Siemens 5WK43125 VW51	
Volkswagen	Polo/Passat	1C0 909 605 A 5WK43122 VW51	68HC908AZ32
Volkswagen	Sharan	1C0 909 605 Siemens 5WK43121	68HC08AZ32
Volkswagen	Touran	1T0 909 605 5WK43150 VW62	68HC912D60
Volkswagen	Touran	1T0 909 605 C 5WK43158 VW62	68HC912D60
			
Volvo		9130529 MC68HC11KA9	68HC11KA9
Volvo		30617708A Temic	68HC912B32
Volvo	S40	0 285 001 146 Bosch 30855881 B	68HC11E9
Volvo	S40	30613471F Temic	68HC11KA4
Volvo	S60	0 285 001 655 Bosch	CR16MCS9
Volvo	S70	0 285 001 220 Bosch 9459151	68HC11E20
Volvo	S80	0 285 001 254 Bosch	CR16MCS9
Volvo	V40	30613498A Temic	68HC11KS2
Volvo	V40	30612702D 6201 Temic	68HC11KA2
Volvo	V40	30613471F Temic	68HC11KA4
Volvo	V40	30613048A Temic	68HC912B32
Volvo	V40	30613047A Temic	68HC912B32

Auto Consulting

Volvo	V50	8697679 Temic	MC9SDG128E
Volvo	V70	30613048A Temic	68HC912B32

Auto Consulting